



1. Name of each part

1) Measuring unit



- ① Digital Meter
- ② Power Switch
- ③ Control Switch for offset (10T)
- ④ Control Switch for gain (10T)
- ⑤ Head Cable Connection
- ⑥ Output for Recorder
- ⑦ Power Supply Connection
- ⑧ Fuse
- ⑨ Name plate

2) Sensor Head



3) Emissivity standard piece

